



Electrical Installation Condition Report

Requirements for Electrical Installations - BS 7671:2018+A2:2022 as amended (IET Wiring Regulations 18th Edition)

Guidance for recipients:

This report is an important and valuable document which should be retained for future reference.

- 1. The purpose of this Report is to confirm, so far as reasonably practicable, whether or not the electrical installation is in a satisfactory condition for continued service (see Section E). The Report should identify any damage, deterioration, defects and/or conditions which may limitations of this inspection, be fully identified. Such give rise to danger (see Section K).
- 2. This Report is only valid if accompanied by the Inspection Schedule(s) and the Schedule(s) of Circuit Details and Test Results.
- 3. The person ordering the Report should have received the original Report and the inspector should have retained a duplicate.
- 4. The original Report should be retained in a safe place and be made available to any person inspecting or undertaking work on the electrical installation in the future. If the property is vacated, this Report will provide the new owner / occupier with details of the condition of the electrical installation at the time the Report was issued.
- 5. Section D (Extent and Limitations) should identify fully the extent of the installation covered by this Report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the Report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.
- 6. Some operational limitations such as inability to gain access to parts of the installation or an item of equipment may have been encountered during the inspection. The inspector should have noted these in Section D.
- 7. For items classified in Section K as C1 ("Danger Present"), the safety of those using the installation is at confirm it is in operational condition in accordance with risk, and it is recommended that a skilled person or persons competent in electrical installation work undertakes the necessary remedial work immediately.
- 8. For items classified in Section K as C2 ("Potentially Dangerous"), the safety of those using the installation may be at risk and it is recommended that a skilled person or persons competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

- 9. Where it has been stated in Section K that an observation requires further investigation code FI the inspection has revealed an apparent deficiency which may result in a code C1 or C2 could not, due to the extent or observations should be investigated as soon as possible. A further examination of the installation will be necessary, to determine the nature and extent of the apparent deficiency (see Section F).
- 10. For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons competent in such work. The recommended date by which the next inspection is due is stated in Section F of the Report under 'Recommendations' and on a label at or near to the consumer unit /distribution board (where required).
- 11. Where the installation includes a residual current device (RCD) it should be tested six-monthly by pressing the button marked 'T' or 'Test'. The device should switch off the supply and should then be switched on to restore the supply. If the device does not switch off the supply when the button is pressed, seek expert advice. For safety reasons it is important that this instruction is followed.
- 12. Where the installation includes an arc fault detection device (AFDD) having a manual test facility it should be tested six-monthly by pressing the test button. Where an AFDD has both a test button and automatic test function, manufacturer's instructions shall be followed with respect to test button operation.
- 13. Where the installation includes a surge protective device (SPD) the status indicator should be checked to manufacturer's information. If the indication shows that the device is not operational, seek expert advice. For safety reasons it is important that this instruction is followed.
- 14. Where the installation includes alternative or additional sources of supply, warning notices should be found at the origin or meter position or, if remote from the origin, at the consumer unit or distribution board and at all points of isolation of all sources of supply.

ELECTRICAL INSTALLATION CONDITION REPORT

FT/EICR 9932000001209

Requirements for Electrical Installations BS 7671:2018+A2:2022 as amended (IET Wiring Regulations 18th Edition)





Client	Nick Webb	Installation	
Address	Flat 3, St. Davids Court St. Johns Hill BARMOUTH Gwynedd	Address	Flat 3, St. Davids Court St. Johns Hill BARMOUTH Gwynedd
Postcode	LL42 1AF	Postcode	LL42 1AF
ason for Produ	icing this Report This form is to be used only	for reporting on the conditi	on of an existing installation.
Clients Request			
Date(s) on which the	e inspection and testing were carried out 16/01/2025	to 16/01/2025	
tails of Installa	tion which is the Subject of this Report		
	ses Residential or Similar V Commercial	Industrial Other (please	specify)
Estimated age of the			
Evidence of alteration		parent if 'Yes', estimat	edyears
Records of installation		ds held by	
Date of last inspection		n Certificate No. or previous Ins	pection Report No.
tent of Electric	al Installation Covered by this Report:		
All Fixed Wiring			
Agreed Limitations	s and Operational Limitations (Regulations 653.2)		
	I, No moving furniture		
Agreed with: Nick	Webb Extent of Term	ination Sampling: 20%	
The inspection and			n accordance with BS 7671: 2018 (IET Wiring Regulation
11.01.			n accordance with BS 7671: 2018 (IET Wiring Regulation
The inspection and amended to 2022 t should be noted that	testing detailed within this report and accompanying so	chedule has been carried out in	re fabric of the building or underground have NOT been inspected
The inspection and amended to 2022 t should be noted that unless specifically agree	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in eed between the client and inspector prior to the inspection. An i	chedule has been carried out in a roof spaces and generally within the inspection should be made within an	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment.
The inspection and amended to 2022 t should be noted that unless specifically agreemmary of the C	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An incondition of the Installation	chedule has been carried out in	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment.
The inspection and amended to 2022 t should be noted that unless specifically agreemmary of the C	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An i	chedule has been carried out in roof spaces and generally within the inspection should be made within are trall assessment of the installation.	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment.
The inspection and amended to 2022 t should be noted that unless specifically agreemmary of the Congeneral conditions	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An incondition of the Installation	chedule has been carried out in roof spaces and generally within the inspection should be made within are trall assessment of the installation.	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment.
The inspection and amended to 2022 t should be noted that unless specifically agreemmary of the Congeneral conditions	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An incondition of the Installation	chedule has been carried out in roof spaces and generally within the inspection should be made within are trall assessment of the installation.	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment.
The inspection and amended to 2022 It should be noted that unless specifically agreemmary of the Congeneral conditions. Satisfactory	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An incondition of the Installation	chedule has been carried out in a roof spaces and generally within the inspection should be made within are erall assessment of the installations of its suitability for continued	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. On in SATISFACTORY *UNSATISFACTORY* use
The inspection and amended to 2022 It should be noted that unless specifically agreemmary of the Congeneral conditions. Satisfactory	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An inspection of the Installation of the Installation of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or p	chedule has been carried out in a roof spaces and generally within the inspection should be made within are erall assessment of the installations of its suitability for continued	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. On in SATISFACTORY *UNSATISFACTORY* use
The inspection and amended to 2022 It should be noted that unless specifically agreemmary of the Commendations The inspection and 2022 The insp	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An incondition of the Installation of the installation of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or put installation of the suitability of the installation for continued use above.	chedule has been carried out in roof spaces and generally within the inspection should be made within an erall assessment of the installations of its suitability for continued otentially dangerous (code C2) cover is stated as UNSATISFACTOR	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. On in SATISFACTORY *UNSATISFACTORY onditions have been identified
The inspection and amended to 2022 It should be noted that unless specifically agreemmary of the Commendations Satisfactory TAN UNSATISFACTO Commendation Where the overall assorbesent' (code C1) or required' (code FI). Other	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An incondition of the Installation of the installation of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or public terms of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of upper continued use as the protection of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued use as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued upon as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued upon as 'Potential dangerous' (code C3) are acted upon as a matter of upper continued upon as 'Potential dangerous' (code C3) are acted upon as 'Potential dangerous' (c	chedule has been carried out in a roof spaces and generally within the respection should be made within an erall assessment of the installations of its suitability for continued otentially dangerous (code C2) cover is stated as UNSATISFACTOR progency. Investigation without delay should be given due consideration.	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. On in SATISFACTORY SUNSATISFACTORY Onditions have been identified At I/we recommend that any observations classified as 'Danger is recommended for observations identified as 'Further Investigations'.
The inspection and amended to 2022 It should be noted that unless specifically agreemmary of the Commendation The inspection and 2022 It should be noted that unless specifically agreemmary of the Commendations The inspection and the commendation of the commendat	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in seed between the client and inspector prior to the inspection. An incondition of the Installation of the installation of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or possessment of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of the installation for continued use ab 'Potential dangerous' (code C2) are acted upon as a matter of the suitability of	chedule has been carried out in roof spaces and generally within the respection should be made within an erall assessment of the installations of its suitability for continued otentially dangerous (code C2) cover is stated as UNSATISFACTOR propercy. Investigation without delay	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. On in SATISFACTORY SUNSATISFACTORY Onditions have been identified At I/we recommend that any observations classified as 'Danger is recommended for observations identified as 'Further Investigations'.
The inspection and amended to 2022 It should be noted that unless specifically agreemmary of the Commendation The inspection and 2022 It should be noted that unless specifically agreemmary of the Commendations The inspection and the commendation of the commendat	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An incondition of the Installation of the installation of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or put the installation of the suitability of the installation for continued use ab "Potential dangerous" (code C2) are acted upon as a matter of upper particular of the suitability of the installation for continued use ab "Potential dangerous" (code C2) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper parti	chedule has been carried out in a roof spaces and generally within the respection should be made within an erall assessment of the installations of its suitability for continued otentially dangerous (code C2) cover is stated as UNSATISFACTOR progency. Investigation without delay should be given due consideration.	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. On in SATISFACTORY SUNSATISFACTORY Onditions have been identified At I/we recommend that any observations classified as 'Danger is recommended for observations identified as 'Further Investigations'.
The inspection and amended to 2022 It should be noted that unless specifically agreemmary of the Commendation The inspection and 2022 It should be noted that unless specifically agreemmary of the Commendations The inspection and the commendation of the commendat	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An incondition of the Installation of the installation of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or put the installation of the suitability of the installation for continued use ab "Potential dangerous" (code C2) are acted upon as a matter of upper particular of the suitability of the installation for continued use ab "Potential dangerous" (code C2) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper particular dangerous (code C3) are acted upon as a matter of upper parti	chedule has been carried out in a roof spaces and generally within the respection should be made within an erall assessment of the installations of its suitability for continued otentially dangerous (code C2) cover is stated as UNSATISFACTOR progency. Investigation without delay should be given due consideration.	ne fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. On in SATISFACTORY SUNSATISFACTORY Onditions have been identified At I/we recommend that any observations classified as 'Danger is recommended for observations identified as 'Further Investigations'.
The inspection and amended to 2022 It should be noted that unless specifically agree mmary of the Commendations. Satisfactory "An UNSATISFACTO commendation Where the overall assoresent" (code C1) or required (code FI). Ot recommend that the in None installation is colored to the commendation of the commendation where the overall assoresent (code FI). Other commend that the in None installation is colored to the commendation where the overall assoresent (code FI). Other commendation is colored to the commendation is colored to the commendation in the colored to the commendation is colored to the co	cables concealed within trunkings and conduits, under floors, in eed between the client and inspector prior to the inspection. An incondition of the Installation of the installation of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or pushessment of the suitability of the installation for continued use ab "Potential dangerous" (code C2) are acted upon as a matter of uppervations classified as "Improvement recommended" (code C3 installation is further inspected and tested by 16/01/2030 to a satisfactory standard.	chedule has been carried out in a roof spaces and generally within the result assessment of the installations of its suitability for continued otentially dangerous (code C2) cover is stated as UNSATISFACTOR (argency, Investigation without delay should be given due consideration (date) for the following reasons:	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. On in SATISFACTORY SUNSATISFACTORY SUNSATISFACTORY SUSPENDING TO THE PROPERTY OF THE PROPERTY O
The inspection and amended to 2022 It should be noted that unless specifically agreement of the Commendation of the Commendat	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in seed between the client and inspector prior to the inspection. An incondition of the Installation Ore of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or pushes the condition of the suitability of the installation for continued use ab electrical dangerous' (code C2) are acted upon as a matter of upoervations classified as 'Improvement recommended' (code C3 installation is further inspected and tested by 16/01/2030 to a satisfactory standard. (s) responsible for the inspection and testing of the electrical installation dare when carrying out the inspection and testing herebassessment of the condition of the electrical installation taking in	chedule has been carried out in proof spaces and generally within the inspection should be made within an exall assessment of the installations of its suitability for continued to tentially dangerous (code C2) converses the stated as UNSATISFACTOR (corport). Investigation without delay should be given due consideration (date) for the following reasons:	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. The in SATISFACTORY *UNSATISFACTORY* *UNSATISFACTORY* Onditions have been identified Onditions have been identified Onditions have been identified Onditions have been identified Onditions have been identified as 'Further Investigate is recommended for observations identified as 'Further Investigate in Subject to the necessary remedial action being taken, I/we instance below), particulars of which are described above, having is report, including the observations and the attached schedules, itations in section D of this report.
The inspection and amended to 2022 It should be noted that unless specifically agreement of the Commendation of the Commendat	cables concealed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in seed between the client and inspector prior to the inspection. An incondition of the Installation Over the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or pusesment of the suitability of the installation for continued use abovervations classified as 'Improvement recommended' (code C3) astallation is further inspected and tested by 16/01/2030 to a satisfactory standard. (s) responsible for the inspection and testing of the electrical installation care when carrying out the inspection and testing heretassessment of the condition of the electrical installation taking in Elliott Electrical	chedule has been carried out in proof spaces and generally within the inspection should be made within an example of the installations of its suitability for continued to tentially dangerous (code C2) converses to the continued stated as UNSATISFACTOR or the continued stated as UNSA	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. The in SATISFACTORY *UNSATISFACTORY* The inspect of the satisfactory *UNSATISFACTORY* Conditions have been identified The inspect of the satisfactory *UNSATISFACTORY* The inspect of the satisfactory is a satisfactory in the satisfactory is recommended for observations identified as 'Further Investigat' in Subject to the necessary remedial action being taken, I/we satisfactory in the inspect of the satisfactory in the satisfactory is report, including the observations and the attached schedules, it attached by Authorised for issue by Authorised for issue by
The inspection and amended to 2022 It should be noted that unless specifically agree mmary of the Commendations of the Commendation where the overall associated in the commendation where the overall associated in the commendation of the commendation where the overall associated in the commendation of the commendation where the overall associated in the commendation of the commendation is commended in the commendation in the commendation is commendation in the c	cables concealed within trunkings and conduits, under floors, in eed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector to the inspector to the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or put in the suitability of the installation for continued use ab "Potential dangerous" (code C2) are acted upon as a matter of upper various classified as "Improvement recommended" (code C3 installation is further inspected and tested by 16/01/2030 to a satisfactory standard. (s) responsible for the inspection and testing of the electrical installation taking in Elliott Electrical Elliott Electrical	chedule has been carried out in proof spaces and generally within the inspection should be made within an exall assessment of the installations of its suitability for continued to tentially dangerous (code C2) converses the stated as UNSATISFACTOR (corport). Investigation without delay should be given due consideration (date) for the following reasons:	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. The in SATISFACTORY *UNSATISFACTORY* *UNSATISFACTORY* Onditions have been identified Onditions have been identified Onditions have been identified Onditions have been identified Onditions have been identified as 'Further Investigate is recommended for observations identified as 'Further Investigate in Subject to the necessary remedial action being taken, I/we instance below), particulars of which are described above, having is report, including the observations and the attached schedules, itations in section D of this report.
The inspection and amended to 2022 the should be noted that unless specifically agreemmary of the Commendation Statisfactory "An UNSATISFACTO Commendation Where the overall assorbesent" (code C1) or required (code FI). Other commend that the interpretation is colored to the commendation of the commendation is colored to the col	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in seed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection (code C1) are cated upon as a matter of upon and the suitability of the installation for continued use ab inspection in the suitability of the installation for continued use ab inspection in the suitability of the installation for continued use ab inspection and tested upon as a matter of upon and inspection in the suitability of the inspection and tested upon as a matter of upon as a mat	chedule has been carried out in proof spaces and generally within the inspection should be made within an erall assessment of the installations of its suitability for continued otentially dangerous (code C2) cover is stated as UNSATISFACTOF argency. Investigation without delay 3) should be given due consideration (date) for the following reasons: (date) (d	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. The in SATISFACTORY *UNSATISFACTORY* The inspect of the satisfactory *UNSATISFACTORY* Conditions have been identified The inspect of the satisfactory *UNSATISFACTORY* The inspect of the satisfactory is a satisfactory in the satisfactory is recommended for observations identified as 'Further Investigat' in Subject to the necessary remedial action being taken, I/we satisfactory in the inspect of the satisfactory in the satisfactory is report, including the observations and the attached schedules, it attached by Authorised for issue by Authorised for issue by
The inspection and amended to 2022 It should be noted that unless specifically agree mmary of the Commendations of the Commendation where the overall assoresent' (code C1) or required' (code C1) or required' (code C1) or required that the in None installation is colored to the commendation of the commend	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in seed between the client and inspector prior to the inspection. An incondition of the Installation Ore of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or pushes essment of the suitability of the installation for continued use ab "Potential dangerous" (code C2) are acted upon as a matter of uservations classified as "Improvement recommended" (code C3 installation is further inspected and tested by 16/01/2030 to a satisfactory standard. (s) responsible for the inspection and testing of the electrical installation taking in Elliott Electrical 73 Llwyn Ynn, TALYBONT,	chedule has been carried out in proof spaces and generally within the inspection should be made within an example of the installations of its suitability for continued to tentially dangerous (code C2) converses to the continued stated as UNSATISFACTOR or the continued stated as UNSA	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. The in SATISFACTORY *UNSATISFACTORY* The inspect of the satisfactory *UNSATISFACTORY* Conditions have been identified The inspect of the satisfactory *UNSATISFACTORY* The inspect of the satisfactory is a satisfactory in the satisfactory is recommended for observations identified as 'Further Investigat' in Subject to the necessary remedial action being taken, I/we satisfactory in the inspect of the satisfactory in the satisfactory is report, including the observations and the attached schedules, it attached by Authorised for issue by Authorised for issue by
The inspection and amended to 2022 It should be noted that unless specifically agree mmary of the Commendation (Commendation (C	testing detailed within this report and accompanying so cables concealed within trunkings and conduits, under floors, in each between the client and inspector prior to the inspection. An incondition of the Installation Over the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or pussessment of the suitability of the installation for continued use abovervations classified as 'Improvement recommended' (code C3 astallation is further inspected and tested by 16/01/2030 to a satisfactory standard. (s) responsible for the inspection and testing of the electrical installation dare when carrying out the inspection and testing here assessment of the condition of the electrical installation taking in Elliott Electrical 73 Llwyn Ynn, TALYBONT, LL43 2AG	chedule has been carried out in proof spaces and generally within the inspection should be made within an exall assessment of the installations of its suitability for continued notentially dangerous (code C2) converses stated as UNSATISFACTOF or unsuitability for continued notentially dangerous (code C2) converses stated as UNSATISFACTOF or unsuitability for the following reasons: Cole	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. The in the satisfactory with the satisfactory and the satisfactory with the satisfactory and the satisfactory are satisfactory with the satisfactory and satisfactory and the satisfactory and the satisfactory and the sa
The inspection and amended to 2022 It should be noted that unless specifically agree mmary of the Commendation of the Commend	cables concealed within trunkings and conduits, under floors, in eed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector to the inspection and testing of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or prior inspection and testing for continued use ab inspection in for continued use ab inspection in the suitability of the installation for continued use ab inspection in an antition of inspection in the inspection in the inspection in the inspection and testing of the electrical installation taking in the inspection in the inspection and testing in the inspection in the inspection in the inspection and testing in the inspection in the inspection in the inspection and testing in the inspection in the inspection in the inspection and testing in the inspection in the inspection and testing in the inspection in the inspection in the inspection and testing in the inspection in the inspection and testing in the inspection in the inspection and testing in the inspection.	chedule has been carried out in roof spaces and generally within the report of the installations of its suitability for continued otentially dangerous (code C2) cover is stated as UNSATISFACTOR (code C2) in the continued of the installation of its suitability for continued otentially dangerous (code C2) cover is stated as UNSATISFACTOR (code C2) in the continued of the installation of the following reasons: Code Elliott	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. The in the satisfactory with a satisfactory and the satisfactory with the satisfactory and the satisfactory with the satisfactory and the satisfactory are satisfactory and the
The inspection and amended to 2022 It should be noted that unless specifically agree mmary of the Commendation (Commendation (C	cables concealed within trunkings and conduits, under floors, in eed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector prior to the inspection. An inceed between the client and inspector to the inspection and testing of the installation (in terms of electrical safety) ORY assessment indicates that dangerous (code C1), or prior inspection and testing for continued use ab inspection in for continued use ab inspection in the suitability of the installation for continued use ab inspection in an antition of inspection in the inspection in the inspection in the inspection and testing of the electrical installation taking in the inspection in the inspection and testing in the inspection in the inspection in the inspection and testing in the inspection in the inspection in the inspection and testing in the inspection in the inspection in the inspection and testing in the inspection in the inspection and testing in the inspection in the inspection in the inspection and testing in the inspection in the inspection and testing in the inspection in the inspection and testing in the inspection.	chedule has been carried out in proof spaces and generally within the inspection should be made within an exall assessment of the installations of its suitability for continued notentially dangerous (code C2) converses stated as UNSATISFACTOF or unsuitability for continued notentially dangerous (code C2) converses stated as UNSATISFACTOF or unsuitability for the following reasons: Cole	the fabric of the building or underground have NOT been inspected a accessible roof space housing other electrical equipment. The in the satisfactory with the satisfactory and the satisfactory with the satisfactory and the satisfactory are satisfactory with the satisfactory and satisfactory and the satisfactory and the satisfactory and the sa

ELECTRICAL INSTALLATION CONDITION REPORT

FT/EICR 9932000001209

Requirements for Electrical Installations BS 7671:2018+A2:2022 as amended (IET Wiring Regulations 18th Edition)





Earthing Arrangements TN-S TN-C-S TT Other Please s	
Number & Type of live conductors AC 🗸 DC 🔃 No. of phases 1	f wires 2
Nature of Supply Parameters (Note: (1) by enquiry, (2) by enquiry or by measurement) Nominal voltage, U/U ₀ (1) 230 v Nominal frequency, f ⁽¹⁾	50 H₂ Confirmation of supply polarity ✓
Prospective fault current, $I_{pf}^{(2)}$ 0.68	0.36 Ω
Supply Protective Device BS (EN) 1361 Fuse HBC 2 Type 2 Rated Current	100 A
No. of Additional Supplies 0	
J. Particulars of Installation Referred to in this Report	Means of Earthing
Details of installation Earth Electrode (where applicable) Type (e.g. rod(s), tape etc)	Distributors facility Installation Earth Electrode
Location N/A Electrode resistance to earth N/A Ω	Maximum Demand (load) 72 Amps ✔ KVA
Main Protective Conductors Material csa	(\checkmark) or Value (\checkmark) or Value
Earthing Conductor Copper 16 mm² Continuity Ve	prified $\begin{tabular}{ c c c c c c c c c c c c c c c c c c c$
Protective Bonding Conductor Copper 10 mm² Continuity Ve	erified \checkmark Ω Connection Verified \checkmark Ω
Material csa (connection / continuity)	(\checkmark) or Value (\checkmark) or Value
Main Supply Conductor Copper 25 mm² Water installation	$lacksquare$ Ω To structural steel Ω
Main Switch Location Cupboard Gas installation pipes	\square Ω To lightning protection \square Ω
Fuse/device rating or setting Switch A Voltage rating 230 V Oil installation pipes	Ω Other \square \square \square
If RCD main switch: Rated residual operating current I Δn mA	
BS(EN) 60947-3 No. of Poles 2 Current Rating 100 A Rated time delay	ms Measured operating trip time ms
K. Observations	Explanation of codes
·	Danger present. Risk of Injury. Immediate remedial action required.
Referring to the attached inspection schedule(s) and schedule(s) of circuit details and	Banger present. Nisk of mjury. Immediate remedial action required.
Referring to the attached inspection schedule(s) and schedule(s) of circuit details and test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D.	Potentially dangerous. Urgent remedial action required.
test results, and subject to the limitations specified at the Extent and limitations of	
test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D.	Potentially dangerous. Urgent remedial action required.
test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D. No remedial work required	Potentially dangerous. Urgent remedial action required. Improvement recommended.
test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D. V No remedial work required	Potentially dangerous. Urgent remedial action required. Improvement recommended.
test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D. No remedial work required The following observations are made	Potentially dangerous. Urgent remedial action required. Improvement recommended. Further Investigation required without delay
test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D. No remedial work required The following observations are made	Potentially dangerous. Urgent remedial action required. Improvement recommended. Further Investigation required without delay Code
test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D. No remedial work required The following observations are made Item No. Observation One of the following codes, as appropriate, has been allocated to each of the observations made above	Potentially dangerous. Urgent remedial action required. Improvement recommended. Further Investigation required without delay Code
test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D. No remedial work required The following observations are made Item No. Observation One of the following codes, as appropriate, has been allocated to each of the observations made above responsible for the installation the degree of urgency for remedial action.	Potentially dangerous. Urgent remedial action required. Improvement recommended. Further Investigation required without delay Code
test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D. No remedial work required The following observations are made Item No. Observation One of the following codes, as appropriate, has been allocated to each of the observations made above responsible for the installation the degree of urgency for remedial action. Danger present. Risk of Injury. Immediate remedial action required.	Potentially dangerous. Urgent remedial action required. Improvement recommended. Further Investigation required without delay Code
test results, and subject to the limitations specified at the Extent and limitations of inspection and testing Section D. No remedial work required The following observations are made Item No. Observation One of the following codes, as appropriate, has been allocated to each of the observations made above responsible for the installation the degree of urgency for remedial action. Danger present. Risk of Injury. Immediate remedial action required. Potentially dangerous. Urgent remedial action required.	Potentially dangerous. Urgent remedial action required. Improvement recommended. Further Investigation required without delay Code

ELECTRICAL INSTALLATION CONDITION REPORT - Schedule of Inspections

FT/EICR 9932000001209

Requirements for Electrical Installations BS7671:2018+A2:2022 as amended (IET Wiring Regulations 18th Edition)





ı	Outcomes							
	Acceptable condition:	Unacceptable condition: State	Improvement recommended:	Further Investigation:	Not Verified:	Limitation:	Not Applicable:	Inadequacies: (Items 1.1 - 1.1.5 Only)
		or 🙋	3	(F)	NV	Δ	N/A	8
ı	In the section of the		Beer dele endelsternel en		-t- 04/00/00 Fl -			

In the outcome column use the codes above. Provide additional comment where appropriate. C1/C2/C3 and FI coded items to be recorded in section K of the condition report.

em No.	Description	Outcom
.0 INTAKI	EQUIPMENT (VISUAL INSPECTION ONLY);	
1.1	Service cable	
1.1.1	Service head	
1.1.2	Earthing arrangement	
1.1.3	Meter tails	
1.1.4	Metering equipment	
1.1.5	Isolator (where present)	Ø
1.1.6	Person ordering work/dutyholder notified (Delete as appropriate) NOTE 1 Where inadequacies in the intake equipment are encountered, which may result in a dangerous or potentially dangerous situation, the person ordering the work and/or dutyholder must be informed. It is strongly recommended that the person ordering the work informs the appropriate authority. NOTE 2 For this section only, where inadequacies are found, an X should be put against the appropriate item and a comment made in Section K	
1.2	Consumer's Isolator (where present)	
1.3	Consumer's meter tails	
) Presen	ce of adequate arrangements for other sources such as microgenerators (551.6; 551.7)	
2.1	Presence of adequate arrangements where generator to operate as a switched alternative (551.6)	N/A
2.2	Adequate arrangements where a generating set operates in parallel with the public supply (551.7)	N/A
EARTH	ING / BONDING ARRANGEMENTS (411.3; Chap 54)	
3.1	Presence and condition of distributor's earthing arrangements (542.1.2.1: 542.1.2.2)	
3.2	Presence and condition of earth electrode connection where applicable (542.1.2.3)	N/A)
3.3	Provision of earthing/bonding labels at all appropriate locations (514.13.1)	
3.4	Confirmation of earthing conductor size (542.3; 543.1.1)	
3.5	Accessibility and condition of earthing conductor at MET arrangement (543.3.2)	
3.6	Confirmation of main protective bonding conductor sizes (544.1)	
3.7	Condition and accessibility of main protective bonding conductor connections (543.3.2; 544.1.2)	
3.8	Accessibility and condition of other protective bonding connections (543.3.1: 543.3.2)	
CONS	IMER UNIT(S) / DISTRIBUTION BOARD(S)	
4.1	Adequacy of working space/accessibility to consumer unit/distribution board (132.12; 513.1)	
4.2	Security of fixing (134.1.1)	
4.3	Condition of enclosure(s) in terms of IP rating etc (416.2)	
4.4	Condition of enclosure(s) in terms of fire rating etc (421.1.201; 526.5)	
4.5	Enclosure not damaged/deteriorated so as to impair safety (651.2)	
4.6	Presence of main linked switch (as required by 462.1.201)	
4.7	Operation of main switch(es) (functional check) (643.10)	
4.8	Manual operation of circuit-breakers and RCDs and AFDDs to prove functionality (643.10)	
4.9	Correct identification of circuit details and protective devices (514.8.1; 514.9.1)	
4.10	Presence of RCD six-monthly test notice at or near consumer unit/distribution board, where required (514.12.2)	
4.11	Presence of alternative supply warning notice at or near consumer unit/distribution board (514.15)	
4.12	Presence of of other required labelling (please specify) (Section 514)	
4.13	Compatibility of protective devices, bases and other components; correct type and rating, (No signs of unacceptable thermal damage, arcing or overheating) (411.4; 411.5; 411.6; Sections 432,433)	•
4.14	Single-pole switching or protective devices in line conductor only (132.14.1; 530.3.3)	
4.15	Protection against mechanical damage where cables enter consumer unit/distribution board (522.8.1; 522.8.5; 522.8.11)	
4.16	Protection against electromagnetic effects where cables enter consumer unit/distribution board/enclosures (521.5.1)	
4.17	RCD(s) provided for fault protection -includes RCBO(s) (411.4.204; 411.5.2; 531.2)	
4.18	RCD(s) provided for additional protection/requirements - includes RCBO(s) (411.3.3; 415.1)	
4.19	Confirmation of indication that SPD is functional (651.4)	N/A
4.20	Confirmation that ALL conductor connections, including connections to busbars, are correctly located in terminals and are tight and secure (526.1)	Ø
4.21	Adequate arrangements where a generating set operates as a switched alternative to the public supply (551.6)	N/A
4.22	Adequate arrangements where a generating set operates in parallel with the public supply (551.7)	(NA
FINAL	CIRCUITS	
5.1	Identification of conductors (514.3.1)	
_		
5.2	Cables correctly supported throughout their run (521.10.202; 522.8.5)	

ELECTRICAL INSTALLATION CONDITION REPORT - Schedule of Inspections

T/EICR 9932000001209

Requirements for Electrical Installations BS7671:2018+A2:2022 as amended (IET Wiring Regulations 18th Edition)





5.4			nduit, d	ucting	or trunk	ing (521.10.1). To include in the integrity of conduit	Ø				
	and trunk	ing systems (metallic and plastic)									
5.5		y of cables for current-carrying capacity w	ith rega	rd for t	he type	and nature of installation (Section 523)					
5.0 FIN	IAL CIRCUITS	CONT									
5.6	6 Coordina	tion between conductors and overload pro	tective	device	s (433.	1; 533.2.1)					
5.7		y of protective devices: type and rated cur	rent for	fault p	rotectio	n (411.3)					
5.8	8 Presence	and adequacy of circuit protective condu	ctors (4	11.3.1:	Section	n 543)					
5.9	9 Wiring sy	stem(s) appropriate for the type and natur	e of the	install	ation ar	nd external influences (Section 522)					
5.1	0 Conceale	Concealed cables installed in prescribed zones (see Section D. Extent and limitations) (522.6.202)									
5.1		Cables concealed under floors, above ceilings or in walls/partitions, adequately protected against damage (see Section D.									
	Extent ar	nd limitations) (522.6.204) ADDITIONAL REQUIREMENTS FOR RC	D NOT	EVCE	EDING	20 mA:					
5.12		cket-outlets of rating 32 A or less, unless									
5.12		upply of mobile equipment not exceeding									
		· · · · · · · · · · · · · · · · · · ·				· · ·					
5.12		es concealed in walls at a depth of less that									
5.12		es concealed in walls/partitions containing									
5.12		uits supplying luminaires within domestic (`	iold) pr	emises	(411.3.4)	<u> </u>				
5.12		ng that is accessible to the public (714.411									
5.1	3 Provision	of fire barriers, sealing arrangements and	protec	tion ag	ainst th	ermal effects (Section 527)	<u></u>				
5.1	4 Band II c	ables segregated/separated from Band I c	ables (528.1)							
5.1	5 Cables s	egregated/separated from communication	s cablin	g (528	.2)						
5.1	6 Cables s	egregated/separated from non-electrical s	ervices	(528.3)						
5.17 TI	ERMINATION C	F CABLES AT ENCLOSURES - INDICA	TE EXT	ENT C	F SAM	PLING IN SECTION D OF THE REPORT (SECTION 5	26)				
5.17	7.1 Connecti	ons soundly made and under no undue st	rain (52	6.6)							
5.17	7.2 No basic	insulation of a conductor visible outside e	nclosur	e (526.	.8)						
5.17	7.3 Connecti	ons of live conductors adequately enclose	d (526.	5)							
5.17		ely connected at point of entry to enclosur			hes etc	.) (522.8.5)					
5.1		of accessories including socket-outlets, s									
5.1		of accessories for external influences (51		, aa je		(00.12 (1))					
5.2		y of working space/accessibility to equipm		2 12: 5	13 1)						
5.2		of working space/accessibility to equipmost				1. 530 3 3)					
		NTAINING A BATH OR SHOWER	oridacio	ora oring	y (102.1	4, 550.5.5)					
6.		Il protection for all low voltage (LV) circuits	by BC	D not c	vooodii	og 20 mA (701 411 2 2)					
			_								
6.2		sed as a protective measure, requirements				` '					
6.3		upply units comply with BS EN 61558-2-5		•		·	⊘				
6.4				not required by BS 7671:2018 (701.415.2)							
6.5		ige (e.g. 230 V) socket-outlets sited at leas									
6.6		• • •		ed location in terms of IP rating (701.512.2)							
6.7		of accessories and controlgear etc. for a									
6.8		of current-using equipment for particular		n within the location (701.55)							
7.0 OT		PECIAL INSTALLATIONS OR LOCATIO									
7.		her special installations or locations prese	nt, if an	y. (Red	ord sep	arately the results of particular inspections	(NA)				
	applied.)										
8.0 PR		W VOLTAGE ELECTRICAL INSTALLAT			<u> </u>						
8.			ents an	d recor	nmenda	ations relating to Chapter 82, additional inspection	(NA)				
0.00		ould be added to the checklist.				0					
9.0 50	chedule of Te	sts Result	s to be	recor	ded on	Schedule of Test Results					
9.1	External earth lo	pop impedance, Ze	Yes		9.9	Insulation Resistance between Live Conductors	Yes				
9.2	Installation earth	n electrode	N/A		9.10	Insulation Resistance between Live Conductors & Earth	Yes				
9.3	Prospective fau	t current, I ^{pf}	Yes		9.11	Polarity (prior to energisation)	Yes				
9.4	Continuity of Ea	rth Conductors	Yes		9.12	Polarity (after energisation) including phase sequence	Yes				
9.5	-	cuit Protective Conductors	Yes	9.12 Polarity (after energisation) including phase sequence 9.13 Earth Fault Loop Impedance							
	-		_		Yes						
9.6	Continuity of rin	•	Yes		9.14 RCDs/RCBOs including selectivity						
9.7	Continuity of Pro	ontinuity of Protective Bonding Conductors 9.15 Functional testing of RCD devices									
9.8	Volt drop verifie	d	Yes		9.16	Functional testing of AFDD(s) devices	N/A				
Inspe	ector's Name:	Cole Elliott			Sian	ature:					
				_	٠٠٠.						
Date:		17/01/2025									
				_							

ELECTRICAL INSTALLATION CONDITION REPORT - Circuit Details

FT/EICR 9932000001209

Requirements for Electrical Installations BS7671 :2018+A2:2022 as amended (IET Wiring Regulations 18th Edition)





Client Name	Nick Webb		Installation Address	Nick Webb, Flat 3, St. Davids Court St. Johns Hill,									
Client Addre	riat o, ot. Davids Court ot. Johns riii			BARMOUTH, Gwynedd									
	BARMOUTH, Gwynedd		Postcode	LL42 1AF									
Client Posto	code LL42 1AF												
Distribution board details - Complete in every case		Complete only if the distribution board is not connected directly to the origin of the installation											
SPD Details: Type	(s)* T1 T2 T3† N/A ✓	Overcurrent protective devic	e Supply to distribution board	in from									
Location	Cupboard	for the distribution circuit:	Supply to distribution board	is itotti									
Designation	DB1	No. of phases 1	BS(EN)	Туре	Rating	A							
No. of ways	14	Nominal voltage	V RCD BS(EN)	Туре	Rating	IΔn mA							
		CHEDIII E OE CIDO	LUT DETAIL C										

SCHEDULE OF CIRCUIT DETAILS																
Cir		Тур	Ref	No.	Circuit co	rcuit conductors significant conductors csa (mm²) Saxii Overcurrent			tive de	/ices	Bre	BS 7671 Max. permitted Zs Other Other §	RCD			
Circuit No. and Line			Ref. method	No. of points served	000 (1		Maximum disconnection time (BS 7671)	BS EN	7		Breaking capacity	Other Other §	BS EN	Ϋ́Υ	IΔn	Rat
ψ ō	Circuit designation	Type of wiring		ints	ر ک	СРС	ion (9) 671)	Number	Type No.	Rating (A)	(KA)	(Ω)	Number	Type No.	lΔn (mA)	Rating (A)
1/S	SPARE		:j:			()	(3)			٤	, ,			-		2
2/S	SPARE															
3/S	RCD Module (Split board)										6					
4/S	RCD Module (Split board)										6					
5/S	Sockets Bedroom	A3	С	6	2.5	1.5	0.4	60898 MCB Type B	В	16	6	2.18	61008	AC	30	80
6/S	Sockets Lounge	A3	С	3	2.5	1.5	0.4	60898 MCB Type B		32	6	1.09	61008	AC	30	80
7/S	Lighting	A3	С	14	1	1	0.4	60898 MCB Type B	-	6	6	5.82	61008	AC	30	80
8/S	SPARE															
9/S	RCD Module (Split board)										6					
10/S	RCD Module (Split board)										6					
11/S	Cooker	A3	С	2	6	2.5	0.4	60898 MCB Type B	В	32	6	1.09	61008	AC	30	80
12/S	Kitchen Ring main	A3	С	9	2.5	1.5	0.4	60898 MCB Type B	В	32	6	1.09	61008	AC	30	80
13/S	Boiler	A3	С	2	2.5	1.5	0.4	60898 MCB Type B	В	16	6	2.18	61008	AC	30	80
14/S	Lighting Living Room	A3	С	2	1	1	0.4	60898 MCB Type B	В	6	6	5.82	61008	AC	30	80
		_	_						_							
I		1	1	1	1	I	I	I	1	1	1	I		I	I	1

Wiring Types: A PVC/PVC, B PVC cables in metallic Conduit, C PVC cables in non-metallic Conduit, D PVC cables in metallic trunking, E PVC cables in non-metallic trunking, F PVC/SWA cables, in the conduit, D PVC cables in metallic trunking, E PVC cables in non-metallic trunking, E PVC cables	G SWA/XPLE cables
H Mineral Insulated, MW Metal Work, FM Ferrous Metal, O Other	

* SPD Type. Where a combined T1 + T2 or T2 + T3 device is installed, indicate by ticking both boxes.

t Where a T3 SPD is installed to protect sensitive equipment, enter Details of Circuits, of the Schedule of Test Results. (See Section 534 of BS 7671:2018+A2:2022.)

j: See Table 4A2 of Appendix 4 of BS 7671:2018+A2:2022.

§ Where the maximum permitted earth fault loop impedance value stated in Max Zs column is taken from a source other than the tabulated values given in Chapter 41 of BS 7671:2018+A2:2022, state the source of the data in the appropriate cell for the circuit in the change to Schedule of Test Results

ELECTRICAL INSTALLATION CONDITION REPORT - Test Results

FT/EICR 9932000001209

Requirements for Electrical Installations BS7671 :2018+A2:2022 as amended (IET Wiring Regulations 18th Edition)





Client Name Client Address		Nick Webb							Install	ation Ac	ddre		Nick Webb, Flat 3, St. Davids Court St. Johns Hill, BARMOUTH, Gwynedd LL42 1AF						
		Flat 3, St. D	t. Johns H	Johns Hill Client LL42 1AF		F Installation Postcode													
						Complete only if the distribution board is not connected directly to the origin of the installation Associated RCD (if any): BS (EN)													
Design									ated RCD (If	any):	В	(EN)	,—	Operat	ing at l∆n		ms		
2 00.9								Z _{db}					Ω	Operat	шу ас і <u>д</u> п				
No. of			Supply polari	ty confirmed	Phas	e sequence o	confirmed	l. _F		ı		_							
No. of	ohases 1		SPD: Opera	itional status	confirmed	✓ Not app	licable	I _{pf}		kA No. o	of pole	es			Time delay (if applicable	‡)			
							TEST		ULTS	intanas				22		Man			
ဂ			Circuit imped					(R	nsulation res lecord lower	reading)			Polarity	Max. Measured	RCD testing All RCDs IΔn	button	ual test operation		
Circuit No. and Line	Ri	ng final circuits	only	Fig 8 check	R11	R2 or R2	Test	voltage	L/L, L/N	١	L/E, N	/E	₹		ms	RCD	AFDD		
Line	r1	rn	r2	(✓)	R1 + R2	R2		V	Μ(Ω)		M(Ω)		Zs (Ω)		(√)	(~)		
1/S				N/A									N/A			N/A	N/A		
2/S				N/A									N/A			N/A	N/A		
3/S				N/A					50	50			N/A			N/A	N/A		
4/S				N/A					50	50			N/A			N/A	N/A		
5/S				N/A	1.05		500		>299	>29	9		✓	1.41	36	✓	N/A		
6/S	0.34	0.31	0.50	✓	0.21		500		>299	>29	9		✓	0.93	36	✓	N/A		
7/S				N/A	0.62		250		>200	>20	00		✓	0.98	36	✓	N/A		
8/S				N/A									N/A			N/A	N/A		
9/S				N/A					50	50			N/A			N/A	N/A		
10/S				N/A					50	50			N/A			N/A	N/A		
11/S				N/A	0.25		500		>299	>29	9		✓	0.61	38	✓	N/A		
12/S	0.45	0.44	0.62	✓	0.26		500		>299	>29	9		✓	0.71	38	✓	N/A		
13/S				N/A	0.51		250		>200	>20	00		✓	0.87	38	✓	N/A		
14/S				N/A	0.54		250		>200	>20	00		✓	0.90	38	✓	N/A		
Details of	of circuits and	l/or installed ed	quipment vulnera	able to dam	age when	testing						Date(s)	dead tes	ting 1	6/01/2025 To	16/01/20	025		
RCDs,	Appliance of	circuitry) live tes		6/01/2025 To	16/01/20			
Test instr	ument serial nu	mber(s) Loop im	pedance 2951113	32	Insulation	resistance 2	29511132		Continuity 29	511132		-	2951113		E/Electrode 2951113		<u></u>		
		capital letters		COLE ELLI				\dashv	, [20	Signa	ature [2007110				
	sition Elect		,			6/01/2025				Oigila									