

# YOUR ONESURVEY HOME REPORT

---

## ADDRESS

---

44 Sir Thomas Elder Way  
Kirkcaldy  
KY2 6ZS

## PREPARED FOR

---

Andy Younger

## INSPECTION CARRIED OUT BY:



**ALLIED**  
SURVEYORS  
SCOTLAND

## HOME REPORT GENERATED BY:

oneSURVEY |   
HOME REPORT

# Document Index

| Document               | Status | Prepared By                                 | Prepared On |
|------------------------|--------|---------------------------------------------|-------------|
| Single Survey          | Final  | Dunfermline - Allied Surveyors Scotland Ltd | 10/02/2026  |
| Mortgage Certificate   | Final  | Dunfermline - Allied Surveyors Scotland Ltd | 10/02/2026  |
| Property Questionnaire | Final  | Mr. Andy Younger                            |             |
| EPC                    | Final  | Dunfermline - Allied Surveyors Scotland Ltd | 10/02/2026  |

## Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto [www.onesurvey.org](http://www.onesurvey.org) (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.**

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

P A R T 1 .

# SINGLE SURVEY

---

A report on the condition of the property, with categories  
being rated from 1 to 3.



# Single Survey

Survey report on:

|                           |        |
|---------------------------|--------|
| <b>Surveyor Reference</b> | DD3180 |
|---------------------------|--------|

|                 |                  |
|-----------------|------------------|
| <b>Customer</b> | Mr. Andy Younger |
|-----------------|------------------|

|                        |                                                 |
|------------------------|-------------------------------------------------|
| <b>Selling address</b> | 44 Sir Thomas Elder Way<br>Kirkcaldy<br>KY2 6ZS |
|------------------------|-------------------------------------------------|

|                           |            |
|---------------------------|------------|
| <b>Date of Inspection</b> | 09/02/2026 |
|---------------------------|------------|

|                    |                                                                                 |
|--------------------|---------------------------------------------------------------------------------|
| <b>Prepared by</b> | Jonathan Combe, BSc (Hons) MRICS<br>Dunfermline - Allied Surveyors Scotland Ltd |
|--------------------|---------------------------------------------------------------------------------|

# **SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)**

## **PART 1 - GENERAL**

### **1.1 THE SURVEYORS**

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property.<sup>1</sup>

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

### **1.2 THE REPORT**

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

---

<sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

### **1.3 LIABILITY**

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### **1.4 GENERIC MORTGAGE VALUATION REPORT**

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### **1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES**

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

#### **1.6 INTELLECTUAL PROPERTY**

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### **1.7 PAYMENT**

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### **1.8 CANCELLATION**

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

## **1.9 PRECEDENCE**

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

## **1.10 DEFINITIONS**

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is *The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion*
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

---

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

## **PART 2 – DESCRIPTION OF THE REPORT**

### **2.1 THE SERVICE**

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

### **2.2 THE INSPECTION**

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

### **2.3 THE REPORT**

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

2.3.1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

2.3.2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.

2.3.3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

## 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

## 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

## 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

## 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

*"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an*

*arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion.* In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- \*There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- \*There are no particularly troublesome or unusual legal restrictions;
- \*There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

*“Re-instatement cost” is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form* unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

## 1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

|                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
|--------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Description                    | The subjects comprise a two storey detached villa with single integral garage.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
| Accommodation                  | GROUND FLOOR<br>Hallway, Lounge, Kitchen/Diner and WC<br>FIRST FLOOR<br>Landing, Master Bedroom with En-Suite Shower Room, Three Further Bedrooms and Family Bathroom                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| Gross internal floor area (m2) | Approximately 117m <sup>2</sup> .                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
| Neighbourhood and location     | Lying to the North-West of Kirkcaldy town centre, the subjects are contained within a popular modern private residential development, completed by Bellway Homes Ltd. All essential retail/leisure/educational facilities are available within a short walk, and there are regular bus services nearby.                                                                                                                                                                                                                                                                                                                |
| Age                            | 19 years.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
| Weather                        | Dry and bright. The report should be read in this context.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| Chimney stacks                 | Not applicable.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| Roofing including roof space   | The roof structure is of a timber pitched design, tile clad externally. Internally, there is a moisture barrier, and blown wool insulation materials have been laid between/over joists within the (partly floored) roof void. Access to the attic is via a hatch and drop-down ladder to the ceiling of the first floor landing.<br><br>Roofs are prone to water penetration during adverse weather but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms. |

|                                     |                                                                                                                                                                                                                                                                                                                                                                                                                                |
|-------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Rainwater fittings                  | <p>The property is fitted with uPVC gutters and downpipes.</p> <p>Rainwater fittings were visually inspected with aid of binoculars where required.</p>                                                                                                                                                                                                                                                                        |
| Main walls                          | <p>The main building is of timber frame construction, with a brick/block outer leaf, which is mainly roughcast externally.</p> <p>Foundations and concealed parts were not exposed or inspected.</p> <p>Walls were visually inspected with the aid of binoculars where required.</p>                                                                                                                                           |
| Windows, external doors and joinery | <p>Windows and doors throughout the property are predominantly uPVC framed double-glazed installations, with the front and side entrance doors being in timber/glass. Fascias/soffits are in PVC materials.</p> <p>Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible.</p> <p>Windows, external doors and joinery were visually inspected.</p> |
| External decorations                | <p>The aforementioned timbers have a paint/stain finish.</p> <p>External decorations were visually inspected.</p>                                                                                                                                                                                                                                                                                                              |
| Conservatories / porches            | Not applicable.                                                                                                                                                                                                                                                                                                                                                                                                                |
| Communal areas                      | Not applicable.                                                                                                                                                                                                                                                                                                                                                                                                                |
| Garages and permanent outbuildings  | <p>There is a single integral garage with metal roller door. The walls and ceiling are plasterboard lined; the floor is in concrete; and the pedestrian door is in timber.</p> <p>Visually inspected.</p>                                                                                                                                                                                                                      |
| Outside areas and boundaries        | <p>There are private garden grounds lying to the front, sides and rear of the property, with apparent boundaries being formed primarily by timber fencing. There is a block paved driveway to the front of the property.</p> <p>Visually inspected.</p>                                                                                                                                                                        |
| Ceilings                            | <p>The ceilings in the property are constructed with plasterboard, with those in the bathroom and en-suite being panel clad.</p> <p>Ceilings were visually inspected from floor level.</p>                                                                                                                                                                                                                                     |
| Internal walls                      | <p>Internal walls are predominantly plasterboard lined, with those in the bathroom and en-suite being part tiled.</p> <p>Internal walls were visually inspected from floor level and a damp meter was used as part of the inspection method.</p>                                                                                                                                                                               |
| Floors including sub floors         | <p>Flooring at ground level is of solid concrete construction, with those serving the upper level being of suspended timber joist construction.</p> <p>Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.</p>                                                                                                                                                                      |

|                                       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
|---------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Internal joinery and kitchen fittings | <p>The kitchen features floor/wall mounted units, incorporating a stainless steel sink and gas hob. Integrated appliances include a fridge/freezer, dishwasher and oven. The utility area to the rear of the garage features similar units. Pass doors are in timber/glass. Skirtings/facings etc. are in timber, and there is adequate storage provision throughout.</p> <p>Internal joinery and kitchen fittings were visually inspected. No stored items were moved during the inspection.</p>                                                                                                                                                                                                                                                                                                                   |
| Chimney breasts and fireplaces        | Not applicable.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| Internal decorations                  | <p>Decorated areas include walls, ceilings, doors, skirtings, facings etc.</p> <p>Visually inspected.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| Cellars                               | Not applicable.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| Electricity                           | <p>The property is served by a mains electricity supply, with the consumer unit being located in the garage.</p> <p>No tests were carried out as part of the inspection.</p> <p>Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.</p> <p>It is recommended good practice that all electrical installations should be checked periodically, approximately every ten years or when a property changes hands. This should be regarded as a routine safety and maintenance check.</p> |
| Gas                                   | <p>The property is supplied with mains gas.</p> <p>No tests were carried out on the gas system during the inspection. Accessible parts of the system were visually inspected without removing fittings. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on. All gas appliances should be tested and thereafter regularly maintained by a Gas Safe registered contractor.</p>                                                                                                                                                                                                                                                            |
| Water, plumbing and bathroom fittings | <p>The property is served by a mains water supply. The bathroom, en-suite and WC contain white sanitaryware.</p> <p>Visual inspection of the accessible pipework, water tanks, cylinders and fittings was carried out without removing any insulation.</p> <p>No tests whatsoever were carried out to the system or appliances.</p> <p>Concealed areas around baths and shower trays cannot be inspected however water spillage over a period of time can result in unexpected defects to hidden parts of the building fabric.</p>                                                                                                                                                                                                                                                                                  |

|                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
|--------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Heating and hot water          | <p>Central heating is provided by a Worcester Greenstar wall mounted gas boiler, which is located within the garage. This serves panel radiators throughout the property, and also provides domestic hot water in conjunction with a storage cylinder, which is located within a cupboard on the first floor landing.</p> <p>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.</p> <p>It is recommended good practice that gas boilers are serviced on an annual basis by an appropriately qualified person. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| Drainage                       | <p>The property is served by mains drainage, discharging into the main sewer.</p> <p>No tests were carried out on the drainage system. Drainage covers etc. were not lifted. Neither drains nor drainage systems were tested. Drainage was visually inspected.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| Fire, smoke and burglar alarms | <p>There are smoke alarms on ceilings within the property. Where not already installed, smoke/heat alarms should be fitted and regularly tested in line with current Safety Standards.</p> <p>No test whatsoever were carried out to any systems or appliances.</p> <p>There is now a requirement in place for compliant interlinked fire, smoke and heat detectors in residential properties. The new fire smoke and alarm standard came into force in Scotland in February 2022, requiring a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also requires to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon fuelled appliance such as a boiler, open fire or wood burner etc. a carbon monoxide detector is also required.</p> <p>The surveyor will only comment on the presence of a smoke detector etc. but will not test them, ascertain if they are in working order, interlinked and / or fully compliant with the fire and smoke alarm standard that was introduced in 2022. We have for the purposes of the report, assumed the system is fully compliant, if not then the appropriate compliant system will required to be installed prior to sale. This of course should be confirmed by your legal advisor.</p> |

|                                            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|--------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>Any additional limits to inspection</p> | <p>It was not possible to inspect floor surfaces, due to the presence of fitted floor coverings, and no sub-floor inspections could be carried out as there was no known access. Our inspection of structural roof timbers within the attic was severely impeded by the depth of the insulation material, as well as the extent to which this area has been floored. Our inspection of this area was limited to a partial inspection only.</p> <p>An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.</p> <p>Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.</p> |
|--------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

## Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

## 2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the above 3 categories:

| Category 3                                                                                                                                                                                               | Category 2                                                                          | Category 1                               |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

|                     |                                                                                                                                                                                                                                                                           |
|---------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Structural movement |                                                                                                                                                                                                                                                                           |
| Repair category:    | 1                                                                                                                                                                                                                                                                         |
| Notes:              | There is evidence of settlement having occurred within the structure at some point in the past. This is not, however, inconsistent with properties of this age and type, and, from our single site inspection, does not appear to be of a serious nor progressive nature. |

|                               |                                                                                                                                                                                     |
|-------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Dampness, rot and infestation |                                                                                                                                                                                     |
| Repair category:              | 1                                                                                                                                                                                   |
| Notes:                        | There is no sign of any of these defects to visible/accessible areas within the property. Readings taken with an electronic moisture meter failed to return any positive registers. |

|                  |                 |
|------------------|-----------------|
| Chimney stacks   |                 |
| Repair category: |                 |
| Notes:           | Not applicable. |

| Category 3                                                                                                                                                                                               | Category 2                                                                          | Category 1                               |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

| Roofing including roof space |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Repair category:             | 1                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| Notes:                       | <p>No immediate action appears to be required. Regular works of repair/maintenance - including repointing - should, however, be anticipated to all roofing areas.</p> <p>Concrete tiles are typically guaranteed for 30 years, but have a reasonable life expectation of around 50/60 years according to the BRE. Life expectancy will often depend on weathering and damage from the prevailing weather. A reputable Roofing Contractor can advise on life expectancy and repair/replacement costs to all roofing components.</p> |

| Rainwater fittings |                                                                                                                                         |
|--------------------|-----------------------------------------------------------------------------------------------------------------------------------------|
| Repair category:   | 1                                                                                                                                       |
| Notes:             | Vegetation noted in gutters. Connections between sections of guttering and downpipes should be monitored to ensure they are watertight. |

| Main walls       |                                                                                                                                                    |
|------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|
| Repair category: | 2                                                                                                                                                  |
| Notes:           | Cracking noted through roughcast in places. Patch repairs may be anticipated to all external finishes as part of an ongoing maintenance programme. |

| Windows, external doors and joinery |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
|-------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Repair category:                    | 1                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| Notes:                              | <p>Windows and doors appear to be in a condition which is commensurate with their age and type. Older installations may require regular works of repair/maintenance, and ultimate renewal, including to locking mechanisms/handles/seals etc.</p> <p>It should be appreciated that double-glazed windows can be problematic, with, through time, opening mechanisms/seals becoming damaged. It is, therefore, possible that maintenance repairs may be required as part of a normal and ongoing maintenance programme. Misting to double-glazed units may only become apparent during certain weather conditions.</p> |

| Category 3                                                                                                                                                                                               | Category 2                                                                          | Category 1                               |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

|                      |                                                                                                                                                |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------|
| External decorations |                                                                                                                                                |
| Repair category:     | 1                                                                                                                                              |
| Notes:               | No immediate action appears to be required. Regular renewal of these finishes should be undertaken to prevent deterioration to surfaces below. |

|                          |                 |
|--------------------------|-----------------|
| Conservatories / porches |                 |
| Repair category:         |                 |
| Notes:                   | Not applicable. |

|                  |                 |
|------------------|-----------------|
| Communal areas   |                 |
| Repair category: |                 |
| Notes:           | Not applicable. |

|                                    |                                                                                                                                                     |
|------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| Garages and permanent outbuildings |                                                                                                                                                     |
| Repair category:                   | 1                                                                                                                                                   |
| Notes:                             | Within the limits of our inspection, no major defects were noted. Regular works of repair/maintenance should, however, be anticipated to all areas. |

|                              |                                                                                                                                                                                        |
|------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Outside areas and boundaries |                                                                                                                                                                                        |
| Repair category:             | 1                                                                                                                                                                                      |
| Notes:                       | Garden grounds were found to be tidily kept. The condition of all boundary fences etc. should be monitored on an ongoing basis, and works of repair in this regard may be anticipated. |

|                  |                                                                                                                                                                  |
|------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Ceilings         |                                                                                                                                                                  |
| Repair category: | 1                                                                                                                                                                |
| Notes:           | Within the limits of our inspection, there were no defects of a reportable nature. Patch repairs may be anticipated as part of a normal programme of decoration. |

| Category 3                                                                                                                                                                                               | Category 2                                                                          | Category 1                               |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

|                  |                                                                                                                                                                         |
|------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Internal walls   |                                                                                                                                                                         |
| Repair category: | 1                                                                                                                                                                       |
| Notes:           | Within the limits of our inspection, there were no defects of a reportable nature. Again, patch repairs may be anticipated as part of a normal programme of decoration. |

|                             |                                                                 |
|-----------------------------|-----------------------------------------------------------------|
| Floors including sub-floors |                                                                 |
| Repair category:            | 1                                                               |
| Notes:                      | Flooring was found to be generally level and firm to the tread. |

|                                       |                                                                                                                                      |
|---------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|
| Internal joinery and kitchen fittings |                                                                                                                                      |
| Repair category:                      | 1                                                                                                                                    |
| Notes:                                | Kitchen fittings appeared to be functional, although some unit doors are slightly ill-fitting. Normal wear and tear noted elsewhere. |

|                                |                 |
|--------------------------------|-----------------|
| Chimney breasts and fireplaces |                 |
| Repair category:               |                 |
| Notes:                         | Not applicable. |

|                      |                                                                   |
|----------------------|-------------------------------------------------------------------|
| Internal decorations |                                                                   |
| Repair category:     | 1                                                                 |
| Notes:               | The property was found to be in generally fresh decorative order. |

|                  |                 |
|------------------|-----------------|
| Cellars          |                 |
| Repair category: |                 |
| Notes:           | Not applicable. |

| Category 3                                                                                                                                                                                               | Category 2                                                                          | Category 1                               |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

## Electricity

|                  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
|------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Repair category: | 2                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
| Notes:           | <p>Although no major defects were noted, the installation is original from the date of construction, and can now be considered to be semi-modern only. A suitably qualified Electrician can advise on any necessary upgrades.</p> <p>The Institution of Engineering and Technology recommends that inspections/testing should be carried out on a regular basis and on change of occupancy. It should be appreciated that only the most recently constructed/rewired properties will have installations which comply fully with IET Regulations. Any available test certification should be exhibited.</p> |

## Gas

|                  |                                                                                                                                                                              |
|------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Repair category: | 1                                                                                                                                                                            |
| Notes:           | <p>Within the limits of our inspection, no major defects were apparent. Any current test certification should be exhibited. There is damage to the lid of the meter box.</p> |

## Water, plumbing and bathroom fittings

|                  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
|------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Repair category: | 1                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| Notes:           | <p>Sanitary fittings and pipework appeared to be in a serviceable condition, but no testing was carried out.</p> <p>Flooring beneath sanitary fittings was not inspected, however, it should be appreciated that, over time, the build-up of condensation - together with small amounts of leakage from joints between tiling or mastic sealant - can cause deterioration to flooring or wall linings. Repairs in this regard may be required as part of a normal and ongoing maintenance programme.</p> |

## Heating and hot water

|                  |                                                                                                                                                                                                                                  |
|------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Repair category: | 1                                                                                                                                                                                                                                |
| Notes:           | <p>No major defects noted. Any current test certification should be exhibited.</p> <p>It is assumed that the installation complies with all relevant Regulations, most notably with regard to flue/ventilation requirements.</p> |

| Category 3                                                                                                                                                                                               | Category 2                                                                          | Category 1                               |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|------------------------------------------|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

| Drainage         |                                                                               |
|------------------|-------------------------------------------------------------------------------|
| Repair category: | <div>1</div>                                                                  |
| Notes:           | No surface evidence of any defect was apparent at the time of our inspection. |

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

|                                              |   |
|----------------------------------------------|---|
| <b>Structural movement</b>                   | 1 |
| <b>Dampness, rot and infestation</b>         | 1 |
| Chimney stacks                               |   |
| <b>Roofing including roof space</b>          | 1 |
| <b>Rainwater fittings</b>                    | 1 |
| <b>Main walls</b>                            | 2 |
| <b>Windows, external doors and joinery</b>   | 1 |
| <b>External decorations</b>                  | 1 |
| Conservatories / porches                     |   |
| Communal areas                               |   |
| <b>Garages and permanent outbuildings</b>    | 1 |
| <b>Outside areas and boundaries</b>          | 1 |
| <b>Ceilings</b>                              | 1 |
| <b>Internal walls</b>                        | 1 |
| <b>Floors including sub-floors</b>           | 1 |
| <b>Internal joinery and kitchen fittings</b> | 1 |
| Chimney breasts and fireplaces               |   |
| <b>Internal decorations</b>                  | 1 |
| Cellars                                      |   |
| <b>Electricity</b>                           | 2 |
| <b>Gas</b>                                   | 1 |
| <b>Water, plumbing and bathroom fittings</b> | 1 |
| <b>Heating and hot water</b>                 | 1 |
| <b>Drainage</b>                              | 1 |

## Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

## Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

### 3. ACCESSIBILITY INFORMATION

#### Guidance Notes on Accessibility Information

**Three steps or fewer to a main entrance door of the property:** In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

**Unrestricted parking within 25 metres:** For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

|                                                                                        |                                                                     |
|----------------------------------------------------------------------------------------|---------------------------------------------------------------------|
| 1. Which floor(s) is the living accommodation on?                                      | Ground/First                                                        |
| 2. Are there three steps or fewer to a main entrance door of the property?             | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| 3. Is there a lift to the main entrance door of the property?                          | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| 4. Are all door openings greater than 750mm?                                           | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| 5. Is there a toilet on the same level as the living room and kitchen?                 | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| 6. Is there a toilet on the same level as a bedroom?                                   | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| 7. Are all rooms on the same level with no internal steps or stairs?                   | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

## 4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

### Matters for a solicitor or licensed conveyancer

Absolute Ownership assumed.

We are unaware of any easements, servitudes or Rights of Way which may adversely affect the property. This point should be confirmed by reference to the Title Deeds. We are unaware of any adverse planning proposals affecting the subjects although this should be confirmed by obtaining a Property Enquiry Certificate. Any Factoring costs for communal areas within the estate should be ascertained prior to the conclusion of Missives.

Our valuation is made on the assumption that all requisite Local Authority Consents/Certification were obtained for the erection of the dwelling-house.

It is recommended that where repairs, defects or maintenance items have been identified, interested parties make appropriate enquiries in order to satisfy themselves of the potential costs and the extent of the works required prior to submitting a legal Offer to Purchase.

### Estimated re-instatement cost (£) for insurance purposes

£370,000

Three Hundred And Seventy Thousand Pounds. This is for the subject property only and is given solely as a guide. It is recommended that the figure is reviewed annually and in light of any future alterations or additions to ensure that you have adequate cover. Alternatively you should seek specialist advice from your insurer. This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction, on a reinstatement basis, assuming reconstruction of the property in its existing design and materials. Finishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during reconstruction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers are advised.

### Valuation (£) and market comments

£290,000

Two Hundred And Ninety Thousand Pounds.

This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, Title restrictions or servitude rights.

|                       |                                               |
|-----------------------|-----------------------------------------------|
| <b>Report author:</b> | Jonathan Combe, BSc (Hons) MRICS              |
| <b>Company name:</b>  | Dunfermline - Allied Surveyors Scotland Ltd   |
| <b>Address:</b>       | 18a Dickson Street<br>Dunfermline<br>KY12 7SL |
| <b>Signed:</b>        | Electronically Signed: 306396-01bf07be-6608   |

|                 |            |
|-----------------|------------|
| Date of report: | 10/02/2026 |
|-----------------|------------|

P A R T 2 .

# MORTGAGE VALUATION REPORT

---

Includes a market valuation of the property.



# Mortgage Valuation Report

## Mortgage Valuation Report

|                     |                                                 |                                                            |
|---------------------|-------------------------------------------------|------------------------------------------------------------|
| Property:           | 44 Sir Thomas Elder Way<br>Kirkcaldy<br>KY2 6ZS | Client: Mr. Andy Younger<br><br>Tenure: Outright Ownership |
| Date of Inspection: | 09/02/2026                                      | Reference: DD3180                                          |

*This report has been prepared as part of the seller's instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising a potential lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.*

### 1.0 LOCATION

Lying to the North-West of Kirkcaldy town centre, the subjects are contained within a popular modern private residential development, completed by Bellway Homes Ltd. All essential retail/leisure/educational facilities are available within a short walk, and there are regular bus services nearby.

### 2.0 DESCRIPTION 2.1 Age: 19 years.

The subjects comprise a two storey detached villa with single integral garage.

### 3.0 CONSTRUCTION

Timber frame/brick/block walls with pitched/tiled roof.

### 4.0 ACCOMMODATION

#### GROUND FLOOR

Hallway, Lounge, Kitchen/Diner and WC

#### FIRST FLOOR

Landing, Master Bedroom with En-Suite Shower Room, Three Further Bedrooms and Family Bathroom

### 5.0 SERVICES (No tests have been applied to any of the services)

|        |       |              |       |      |       |           |       |
|--------|-------|--------------|-------|------|-------|-----------|-------|
| Water: | Mains | Electricity: | Mains | Gas: | Mains | Drainage: | Mains |
|--------|-------|--------------|-------|------|-------|-----------|-------|

|                  |                                     |
|------------------|-------------------------------------|
| Central Heating: | Full gas fired system to radiators. |
|------------------|-------------------------------------|

### 6.0 OUTBUILDINGS

|         |                  |
|---------|------------------|
| Garage: | Single integral. |
|---------|------------------|

|         |       |
|---------|-------|
| Others: | None. |
|---------|-------|

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                 |                                                                                                                                                                                                               |        |                      |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|
| 7.0                                                                                                                                                                                                                                                                                                                                                                                                                                                              | <b>GENERAL CONDITION</b> - <i>A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.</i>                                                                   |                 |                                                                                                                                                                                                               |        |                      |
| This property appears to be in a condition which is consistent with its age and type of construction. There is evidence of settlement having occurred within the structure at some point in the past, however, on the basis of our single site inspection, this does not appear to be of a serious nor progressive nature. Some works of repair/maintenance are now required to areas, with all factors having been fully reflected within our valuation figure. |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                 |                                                                                                                                                                                                               |        |                      |
| 8.0                                                                                                                                                                                                                                                                                                                                                                                                                                                              | <b>ESSENTIAL REPAIR WORK</b> <i>(as a condition of any mortgage or, to preserve the condition of the property)</i>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                 |                                                                                                                                                                                                               |        |                      |
| None.                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                 |                                                                                                                                                                                                               |        |                      |
| 8.1 Retention recommended:                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                 | --                                                                                                                                                                                                            |        |                      |
| 9.0                                                                                                                                                                                                                                                                                                                                                                                                                                                              | <b>ROADS &amp; FOOTPATHS</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                 |                                                                                                                                                                                                               |        |                      |
| Made.                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                 |                                                                                                                                                                                                               |        |                      |
| 10.0                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>BUILDINGS INSURANCE (£):</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 370,000         | <b>GROSS EXTERNAL FLOOR AREA</b>                                                                                                                                                                              | 134 m2 | <b>Square metres</b> |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | <i>This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.</i>                                                                                                                                                                                                                                                                                                       |                 |                                                                                                                                                                                                               |        |                      |
| 11.0                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>GENERAL REMARKS</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                 |                                                                                                                                                                                                               |        |                      |
| Absolute Ownership assumed.                                                                                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                 |                                                                                                                                                                                                               |        |                      |
| We are unaware of any easements, servitudes or Rights of Way which may adversely affect the property. This point should be confirmed by reference to the Title Deeds. We are unaware of any adverse planning proposals affecting the subjects although this should be confirmed by obtaining a Property Enquiry Certificate. Any Factoring costs for communal areas within the estate should be ascertained prior to the conclusion of Missives.                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                 |                                                                                                                                                                                                               |        |                      |
| Our valuation is made on the assumption that all requisite Local Authority Consents/Certification were obtained for the erection of the dwelling-house.                                                                                                                                                                                                                                                                                                          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                 |                                                                                                                                                                                                               |        |                      |
| It is recommended that where repairs, defects or maintenance items have been identified, interested parties make appropriate enquiries in order to satisfy themselves of the potential costs and the extent of the works required prior to submitting a legal Offer to Purchase.                                                                                                                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                 |                                                                                                                                                                                                               |        |                      |
| 12.0                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>VALUATION</b> <i>On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.</i> |                 |                                                                                                                                                                                                               |        |                      |
| 12.1                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Market Value in present condition (£):</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | <b>£290,000</b> | Two Hundred And Ninety Thousand Pounds. This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, Title restrictions or servitude rights. |        |                      |
| 12.2                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Market Value on completion of essential works (£):</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |                 |                                                                                                                                                                                                               |        |                      |

|                                                    |                                                        |                                             |                                                                                                                                           |            |
|----------------------------------------------------|--------------------------------------------------------|---------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|------------|
| <b>12.3</b>                                        | <b>Suitable security for normal mortgage purposes?</b> | Yes                                         |                                                                                                                                           |            |
| <b>12.4</b>                                        | <b>Date of Valuation:</b>                              | 09/02/2026                                  |                                                                                                                                           |            |
| <b>Signature:</b>                                  |                                                        | Electronically Signed: 306396-01bf07be-6608 |                                                                                                                                           |            |
| <b>Surveyor:</b>                                   | Jonathan Combe                                         | BSc (Hons) MRICS                            | <b>Date:</b>                                                                                                                              | 10/02/2026 |
| <b>Dunfermline - Allied Surveyors Scotland Ltd</b> |                                                        |                                             |                                                                                                                                           |            |
| <b>Office:</b>                                     | 18a Dickson Street<br>Dunfermline<br>KY12 7SL          |                                             | Tel: 01383 728 833<br>Fax:<br>email: <a href="mailto:dunfermline@alliedsurveyorsscotland.com">dunfermline@alliedsurveyorsscotland.com</a> |            |

P A R T 3 .

# ENERGY REPORT

---

A report on the energy efficiency of the property.



# energy report

energy report on:

|                         |                                                 |
|-------------------------|-------------------------------------------------|
| <b>Property address</b> | 44 Sir Thomas Elder Way<br>Kirkcaldy<br>KY2 6ZS |
|-------------------------|-------------------------------------------------|

|                 |                  |
|-----------------|------------------|
| <b>Customer</b> | Mr. Andy Younger |
|-----------------|------------------|

|                         |                                                 |
|-------------------------|-------------------------------------------------|
| <b>Customer address</b> | 44 Sir Thomas Elder Way<br>Kirkcaldy<br>KY2 6ZS |
|-------------------------|-------------------------------------------------|

|                    |                                                                                 |
|--------------------|---------------------------------------------------------------------------------|
| <b>Prepared by</b> | Jonathan Combe, BSc (Hons) MRICS<br>Dunfermline - Allied Surveyors Scotland Ltd |
|--------------------|---------------------------------------------------------------------------------|

# Energy Performance Certificate (EPC)

# Scotland

Dwellings

44 SIR THOMAS ELDER WAY, KIRKCALDY, KY2 6ZS

**Dwelling type:** Detached house  
**Date of assessment:** 09 February 2026  
**Date of certificate:** 10 February 2026  
**Total floor area:** 117 m<sup>2</sup>  
**Primary Energy Indicator:** 138 kWh/m<sup>2</sup>/year

**Reference number:** 0140-2011-5020-2306-1351  
**Type of assessment:** RdSAP, existing dwelling  
**Approved Organisation:** Elmhurst  
**Main heating and fuel:** Boiler and radiators, mains gas

## You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

|                                                   |        |                                                      |
|---------------------------------------------------|--------|------------------------------------------------------|
| Estimated energy costs for your home for 3 years* | £3,357 | See your recommendations report for more information |
| Over 3 years you could save*                      | £      |                                                      |

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions

Very energy efficient - lower running costs



Not energy efficient - higher running costs

| Current | Potential |
|---------|-----------|
| 78      | 82        |

## Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (78)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Very environmentally friendly - lower CO<sub>2</sub> emissions



Not environmentally friendly - higher CO<sub>2</sub> emissions

| Current | Potential |
|---------|-----------|
| 78      | 79        |

## Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (78)**

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

| Recommended measures             | Indicative cost  | Typical savings over 3 years |
|----------------------------------|------------------|------------------------------|
| 1 Solar photovoltaic (PV) panels | £8,000 - £10,000 | £675.00                      |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit [greenerscotland.org](http://greenerscotland.org) or contact Home Energy Scotland on 0808 808 2282.

**THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element               | Description                                                          | Energy Efficiency | Environmental |
|-----------------------|----------------------------------------------------------------------|-------------------|---------------|
| Walls                 | Timber frame, as built, insulated (assumed)                          | ★★★★☆             | ★★★★☆         |
| Roof                  | Pitched, 250 mm loft insulation                                      | ★★★★☆             | ★★★★☆         |
| Floor                 | Solid, insulated (assumed)<br>To unheated space, insulated (assumed) | —<br>—            | —<br>—        |
| Windows               | Fully double glazed                                                  | ★★★☆☆             | ★★★☆☆         |
| Main heating          | Boiler and radiators, mains gas                                      | ★★★★☆             | ★★★★☆         |
| Main heating controls | Programmer, room thermostat and TRVs                                 | ★★★★☆             | ★★★★☆         |
| Secondary heating     | None                                                                 | —                 | —             |
| Hot water             | From main system                                                     | ★★★★☆             | ★★★★☆         |
| Lighting              | Good lighting efficiency                                             | ★★★★☆             | ★★★★☆         |

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

## The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 25 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.9 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

## Estimated energy costs for this home

|               | Current energy costs | Potential energy costs | Potential future savings                                                            |
|---------------|----------------------|------------------------|-------------------------------------------------------------------------------------|
| Heating       | £2,418 over 3 years  | £2,418 over 3 years    |  |
| Hot water     | £720 over 3 years    | £720 over 3 years      |                                                                                     |
| Lighting      | £219 over 3 years    | £219 over 3 years      |                                                                                     |
| <b>Totals</b> | <b>£3,357</b>        | <b>£3,357</b>          |                                                                                     |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

## Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

| Recommended measures                 | Indicative cost  | Typical saving per year | Rating after improvement                                                              |                                                                                       |
|--------------------------------------|------------------|-------------------------|---------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
|                                      |                  |                         | Energy                                                                                | Environment                                                                           |
| 1 Solar photovoltaic panels, 2.5 kWp | £8,000 - £10,000 | £225                    |  |  |

## Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to [www.greenerscotland.org](http://www.greenerscotland.org).

## About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

### 1 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

## Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

## Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

| Heat demand                  | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 8,832.71          | N/A                       | N/A                              | N/A                             |
| Water heating (kWh per year) | 3,078.85          |                           |                                  |                                 |

## About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst ([www.elmhurstenergy.co.uk](http://www.elmhurstenergy.co.uk)), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk) and entering the report reference number (RRN) printed at the top of this page.

|                             |                                                                                                      |
|-----------------------------|------------------------------------------------------------------------------------------------------|
| Assessor's name:            | Mr. Jonathan Combe                                                                                   |
| Assessor membership number: | EES/020089                                                                                           |
| Company name/trading name:  | Allied Surveyors Scotland Ltd                                                                        |
| Address:                    | 18a Dickson Street<br>Dunfermline<br>KY12 7SL                                                        |
| Phone number:               | 01383 738 585                                                                                        |
| Email address:              | <a href="mailto:dunfermline@alliedsurveyorsscotland.com">dunfermline@alliedsurveyorsscotland.com</a> |
| Related party disclosure:   | No related party                                                                                     |

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

## Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk), with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at [www.gov.scot/epc](http://www.gov.scot/epc).

### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greenerscotland.org](https://www.greenerscotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

**HOMEENERGYSCOTLAND.ORG**  
**0808 808 2282**  
FUNDED BY THE SCOTTISH GOVERNMENT



P A R T 4 .

# PROPERTY QUESTIONNAIRE

---

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



## Property Questionnaire

Property Address

44 Sir Thomas Elder Way

Kirkcaldy

KY2 6ZS

Seller(s)

Andy Younger

Completion date of property questionnaire

Note for sellers

|    |                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. | <b>Length of ownership</b>                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|    | <b>How long have you owned the property?</b><br>16 years                                                                                                                                                                                                                                                                                                                                                                                                        |
| 2. | <b>Council tax</b>                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|    | <b>Which Council Tax band is your property in? (Please circle)</b><br><input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input checked="" type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H                                                                                                                                                        |
| 3. | <b>Parking</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
|    | <b>What are the arrangements for parking at your property?</b><br><b>(Please tick all that apply)</b><br><br>Garage <input checked="" type="checkbox"/><br>Allocated parking space <input type="checkbox"/><br>Driveway <input checked="" type="checkbox"/><br>Shared parking <input type="checkbox"/><br>On street <input type="checkbox"/><br>Resident permit <input type="checkbox"/><br>Metered parking <input type="checkbox"/><br>Other (please specify): |

|           |                                                                                                                                                                                                                                         |                                                                                                            |
|-----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|
| <b>4.</b> | <b>Conservation area</b>                                                                                                                                                                                                                |                                                                                                            |
|           | Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?                                      | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO<br><input type="checkbox"/> Don't know |
| <b>5.</b> | <b>Listed buildings</b>                                                                                                                                                                                                                 |                                                                                                            |
|           | Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?                                                                      | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
| <b>6.</b> | <b>Alterations/additions/extensions</b>                                                                                                                                                                                                 |                                                                                                            |
| a         | (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?                                               | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
|           | If you have answered yes, please describe below the changes which you have made:                                                                                                                                                        |                                                                                                            |
|           | (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?                                                                                                                     | <input type="checkbox"/> YES <input type="checkbox"/> NO                                                   |
|           | If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.                                                                           |                                                                                                            |
|           | If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:                                                                                    |                                                                                                            |
| b         | Have you had replacement windows, doors, patio doors or double glazing installed in your property                                                                                                                                       | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
|           | If you have answered yes, please answer the three questions below:                                                                                                                                                                      |                                                                                                            |
|           | (i) Were the replacements the same shape and type as the ones you replaced?                                                                                                                                                             | <input type="checkbox"/> YES <input type="checkbox"/> NO                                                   |
|           | (ii) Did this work involve any changes to the window or door openings?                                                                                                                                                                  | <input type="checkbox"/> YES <input type="checkbox"/> NO                                                   |
|           | (iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):<br><br>Please give any guarantees which you received for this work to your solicitor or estate agent. |                                                                                                            |
| <b>7.</b> | <b>Central heating</b>                                                                                                                                                                                                                  |                                                                                                            |
| a         | Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).           | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO<br><input type="checkbox"/> Partial    |

|            |                                                                                                                                                                                                          |                                                                                                            |
|------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|
|            | <p>If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).</p> <p><i>Gas. Boiler is 3 years old.</i></p> |                                                                                                            |
|            | If you have answered yes, please answer the three questions below:                                                                                                                                       |                                                                                                            |
|            | <p>(i) When was your central heating system or partial central heating system installed?</p> <p><i>Don't know</i></p>                                                                                    |                                                                                                            |
|            | (ii) Do you have a maintenance contract for the central heating system?                                                                                                                                  | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
|            | If you have answered yes, please give details of the company with which you have a maintenance contract                                                                                                  |                                                                                                            |
|            | (iii) When was your maintenance agreement last renewed? (Please provide the month and year).                                                                                                             |                                                                                                            |
| <b>8.</b>  | <b>Energy Performance Certificate</b>                                                                                                                                                                    |                                                                                                            |
|            | Does your property have an Energy Performance Certificate which is less than 10 years old?                                                                                                               | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO                                        |
| <b>9.</b>  | <b>Issues that may have affected your property</b>                                                                                                                                                       |                                                                                                            |
| a          | Has there been any storm, flood, fire or other structural damage to your property while you have owned it?                                                                                               | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
|            | If you have answered yes, is the damage the subject of any outstanding insurance claim?                                                                                                                  | <input type="checkbox"/> YES <input type="checkbox"/> NO                                                   |
| b          | Are you aware of the existence of asbestos in your property?                                                                                                                                             | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO<br><input type="checkbox"/> Don't know |
|            | If you have answered yes, please give details:                                                                                                                                                           |                                                                                                            |
| <b>10.</b> | <b>Services</b>                                                                                                                                                                                          |                                                                                                            |
|            |                                                                                                                                                                                                          |                                                                                                            |

|                                                        |                                                                                                                                                                                                                               |                                                                                                 |                                                                                                            |
|--------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|
| a                                                      | Please tick which services are connected to your property and give details of the supplier:                                                                                                                                   |                                                                                                 |                                                                                                            |
|                                                        | Services                                                                                                                                                                                                                      | Connected                                                                                       | Supplier                                                                                                   |
|                                                        | Gas or liquid petroleum gas                                                                                                                                                                                                   | Y                                                                                               | Utities warehouse                                                                                          |
|                                                        | Water mains or private water supply                                                                                                                                                                                           | Y                                                                                               | Scottish water                                                                                             |
|                                                        | Electricity                                                                                                                                                                                                                   | Y                                                                                               | Utilities warehouse                                                                                        |
|                                                        | Mains drainage                                                                                                                                                                                                                | N                                                                                               |                                                                                                            |
|                                                        | Telephone                                                                                                                                                                                                                     | N                                                                                               |                                                                                                            |
|                                                        | Cable TV or satellite                                                                                                                                                                                                         | N                                                                                               |                                                                                                            |
|                                                        | Broadband                                                                                                                                                                                                                     | N                                                                                               |                                                                                                            |
| b                                                      | Is there a septic tank system at your property?                                                                                                                                                                               |                                                                                                 | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
|                                                        | If you have answered yes, please answer the two questions below:                                                                                                                                                              |                                                                                                 |                                                                                                            |
|                                                        | (i) Do you have appropriate consents for the discharge from your septic tank?                                                                                                                                                 | <input type="checkbox"/> YES <input type="checkbox"/> NO<br><input type="checkbox"/> Don't know |                                                                                                            |
|                                                        | (ii) Do you have a maintenance contract for your septic tank?                                                                                                                                                                 | <input type="checkbox"/> YES <input type="checkbox"/> NO                                        |                                                                                                            |
|                                                        | If you have answered yes, please give details of the company with which you have a maintenance contract:                                                                                                                      |                                                                                                 |                                                                                                            |
| <b>11. Responsibilities for shared or common areas</b> |                                                                                                                                                                                                                               |                                                                                                 |                                                                                                            |
| a                                                      | Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?<br><br>If you have answered yes, please give details:   |                                                                                                 | <input type="checkbox"/> YES <input type="checkbox"/> NO<br><input checked="" type="checkbox"/> Don't know |
| b                                                      | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?<br><br>If you have answered yes, please give details:                                                  |                                                                                                 | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO<br><input type="checkbox"/> N/A        |
| c                                                      | Has there been any major repair or replacement of any part of the roof during the time you have owned the property?                                                                                                           |                                                                                                 | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
| d                                                      | Do you have the right to walk over any of your neighbours' property- for example to put out your rubbish bin or to maintain your boundaries?<br><br>If you have answered yes, please give details:                            |                                                                                                 | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
| e                                                      | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?<br><br>If you have answered yes, please give details: |                                                                                                 | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |

|                                                  |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                                                                            |
|--------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------|
| f                                                | As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.)<br><br>If you have answered yes, please give details:                                                                                                                                                                               | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
| <b>12. Charges associated with your property</b> |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                                                                            |
| a                                                | Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:                                                                                                                                                                                                                                                               | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
| b                                                | Is there a common buildings insurance policy?                                                                                                                                                                                                                                                                                                                                                                                                       | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO<br><input type="checkbox"/> Don't know |
|                                                  | If you have answered yes, is the cost of the insurance included in your monthly/annual factors charges?                                                                                                                                                                                                                                                                                                                                             |                                                                                                            |
| c                                                | Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.<br><br><i>Green belt for local weeding etc.</i>                                                                                                                                                                                                  |                                                                                                            |
| <b>13. Specialist works</b>                      |                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                                                                            |
| a                                                | As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?                                                                                                                                                                                                                                                                                                               | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
|                                                  | If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.                                                                                                                                                                                                                                                                                 |                                                                                                            |
| b                                                | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?                                                                                                                                                                                                                                                                                                                            | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO                                        |
|                                                  | If you have answered yes, please give details:                                                                                                                                                                                                                                                                                                                                                                                                      |                                                                                                            |
| c                                                | If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?                                                                                                                                                                                                                                                                                                                                                         | <input type="checkbox"/> YES <input type="checkbox"/> NO                                                   |
|                                                  | If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.<br>Guarantees are held by: |                                                                                                            |

|            |                                                                                                                                         |                                                             |
|------------|-----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|
| <b>14.</b> | <b>Guarantees</b>                                                                                                                       |                                                             |
| a          | Are there any guarantees or warranties for any of the following:                                                                        |                                                             |
| (i)        | Electrical work                                                                                                                         | [ ] NO [ ] YES [x] Don't know [ ] With title deeds [ ] Lost |
| (ii)       | Roofing                                                                                                                                 | [ ] NO [ ] YES [x] Don't know [ ] With title deeds [ ] Lost |
| (iii)      | Central heating                                                                                                                         | [ ] NO [ ] YES [x] Don't know [ ] With title deeds [ ] Lost |
| (iv)       | National House Building Council(NHBC)                                                                                                   | [ ] NO [ ] YES [x] Don't know [ ] With title deeds [ ] Lost |
| (v)        | Damp course                                                                                                                             | [ ] NO [ ] YES [x] Don't know [ ] With title deeds [ ] Lost |
| (vi)       | Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)                                  | [ ] NO [ ] YES [x] Don't know [ ] With title deeds [ ] Lost |
| b          | If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s): |                                                             |
| c          | Are there any outstanding claims under any of the guarantees listed above?                                                              | [ ] YES [x] NO                                              |
|            | If you have answered yes, please give details:                                                                                          |                                                             |

|                                                          |                                                                                                                                                                                                                     |                                  |
|----------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|
| <b>15.</b>                                               | <b>Boundaries</b>                                                                                                                                                                                                   |                                  |
|                                                          | So far as you are aware, has any boundary of your property been moved in the last 10 years?                                                                                                                         | [ ] YES [x] NO<br>[ ] Don't know |
|                                                          | If you have answered yes, please give details:                                                                                                                                                                      |                                  |
| <b>16.</b>                                               | <b>Notices that affect your property</b>                                                                                                                                                                            |                                  |
| In the past three years have you ever received a notice: |                                                                                                                                                                                                                     |                                  |
| a                                                        | advising that the owner of a neighbouring property has made a planning application?                                                                                                                                 | [ ] YES [x] NO                   |
| b                                                        | that affects your property in some other way?                                                                                                                                                                       | [ ] YES [x] NO                   |
| c                                                        | that requires you to do any maintenance, repairs or improvements to your property?                                                                                                                                  | [ ] YES [x] NO                   |
|                                                          | If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property. |                                  |

**Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.**

Signature(s): Andrew younger

Capacity: ☒ Owner  
☐ Legally Appointed Agent for Owner

Date: 13/02/2026